

REPAIR SHEET

BRAND


RYOBI

MODEL NO.

P661

DESCRIPTION

18 Volt PEX Crimp Ring Press Tool




ONE WORLD TECHNOLOGIES, INC.

P.O. Box 1288, Anderson, SC 29622 ■ 1-800-525-2579 ■ www.ryobitools.com

1-25-21 (Rev:05)


The model number and manufacturing location will be found on a label attached to the product. Always mention this information in all communications regarding this product and when ordering parts.



**P661****PARTS LIST**

KEY NO.	PART NO.	DESCRIPTION	QTY.
1	204800003	Housing Assembly (Inc. Key Nos. 2-4 and 27)	1
2	941007094	Indicator Label	1
3	940114178	Logo Label	1
4	941122082	Data Label	1
5	690924001	Retaining Ring	4
6	673900001	Jaw Pin	2
7	662777001	Screw (M2.3 x 5 mm, T8 Torx Pan Hd.)	2
8	643490001	Jaw Insert (3/8 in., not included)	2
	643491001	Jaw Insert (1/2 in.)	2
	643492001	Jaw Insert (3/4 in.)	2
9	662815002	Screw (M3 x 21.6 mm)	2
10	313731001	Top Jaw Assembly	1
11	697203001	Compression Spring	2
12	662816002	Jaw Nut (M3)	2
13	313731002	Bottom Jaw Assembly	1
14	673880001	Hinge Pin	1

KEY NO.	PART NO.	DESCRIPTION	QTY.
15	697452001	Torsion Spring	1
16	660031017	Screw (M3.5 x 16 mm, T10 Torx Pan Hd.)	9
17	204803002	Screw Assembly	1
18	643484001	Jaw Support	2
19	670974003	Lock Nut (M5)	2
20	662755001	Screw (M5 x 35 mm, Hex. Soc. Hd.)	2
21	564761001	Switch Button	1
22	591858001	Switch Support	1
23	206801002	Gearbox Assembly	1
24	696626001	Belt Clip	1
25	635957001	Gauge	1
26	206802002	Motor, Switch and Circuit Board Assembly	1
27	941120403	Battery Foot Label	1
	Not Shown:		
	995000616	Operator's Manual (961152975)	



WIRING DIAGRAM