

REPAIR SHEET

BRAND


HART

MODEL NO.

HPJS01

DESCRIPTION

20 Volt Jig Saw



HART CONSUMER PRODUCTS, INC.


P.O. Box 1348, Anderson, SC 29622 ■ 1-800-776-5191 ■ www.HARTtools.com

10-11-22 (Rev:04)

The model number and manufacturing location will be found on a label attached to the product. Always mention this information in all communications regarding this product and when ordering parts.



HPJS01





HPJS01


PARTS LIST

KEY NO.	PART NO.	DESCRIPTION	QTY.
1-CN	202029002	Housing Assembly (Inc. Key Nos. 23 & 36-38)	1
1-VN	202029005	Housing Assembly (Inc. Key Nos. 23 & 36-38)	1
2	538580001	Orbital Knob	1
3	680909001	Compression Spring	1
4	550424001	Detent Button	1
5	538581001	Speed Dial	1
6	560174001	O-Ring	1
7	680865001	Washer	1
8	202029003	Switch and Circuit Board Assembly	1
9	560219006	Contact Plate Stopper	1
10	670974003	Lock Nut (M5)	2
11	673054002	Orbital Pin	1
12	CN-206029005	Motor Assembly	1
	VN-206029006	Motor Assembly	1
13	630844001	Washer	1
14	658690001	Drive Plate	1
15	CN-611716001	Balance Block	1
	VN-611716002	Balance Block	1
16	202029004	Gear Box Assembly	1
17	698126001	Drive Bushing	1
18	611841001	Bushing	1
19	304944019	Saw Bar Assembly	1
20	630845001	Slide Guide Plate	1
21	631252001	Spring Plate	1

KEY NO.	PART NO.	DESCRIPTION	QTY.
22	658530001	Guard Wire	1
23-CN	CN-941122289	Data Label	1
	VN-941122827	Data Label	1
24	660031017	Screw (M3.5 x 16 mm, T10 Torx Pan Hd.)	13
25	662035001	Screw (M5 x 25 mm, Hex Soc. Hd.)	2
26	693114003	Torsion Spring	1
27	673058001	Pin	1
28	305061006	Guide Holder Assembly	1
29	313793001	Bracket and Sleeve Assembly	1
30	CN-634908001	Base Plate	1
	VN-634908005	Base Plate	1
31	634911001	Clamp Plate	1
32	661276002	Screw (M5 x 10 mm, Hex. Soc. Hd.)	2
33	694108001	Hex Key Wrench (M4)	1
34	570264001	Rubber Cushion	2
35	636124001	Drive Plate Holder Clip	2
36	941120470	Warning Label	1
37	941114260	Logo Label	1
38	941001780	Orbital Mode Key Label	1
	Not Shown:		
	995000863	Operator's Manual (CN – 961153059) (VN – 961153215)	



HPJS01



WIRING DIAGRAM